

Discontinuance Notice: FSL-751

Due to an obsolescence of a component used in our FSL-751 VIEW detector by one of our component suppliers Notifier is forced to discontinue this device with immediate effect.

Unfortunately, we must reject any unconfirmed open orders and all new orders for FSL-751 VIEW detectors with immediate effect.

We anticipate releasing a direct replacement using new technology shortly which will provide a high sensitivity point detector. This new device will be able to be used as a drop-in replacement for the current FSL-751 VIEW detector.

Availability is expected towards Q4 2018.

Ordering Information:

Item #	Description
FSL-751	FlashScan View™ laser type sensor - off white

Please consult your Notifier Systems Consultant for the recommended alternative to the FSL-751 in an existing or future application.

Resources & Support:

Please contact your Notifier Systems Consultant to discuss specific replacement applications or support questions.

Technical questions should be directed to Notifier technical support. **Tel: 1800 220 345 (Toll Free)**