

IFS-2600 FACP support components temporarily unavailable

Due to obsolescence of supplier components Notifier is temporarily unable to supply the following replacement components for the IFS-2600 Fire Alarm Control Panel.

Item No.	Description
IFS-2600TBRK (ASY-02-020)	IFS-2600 Termination Board Replacement Kit to suit PSI version (PSI not included)

We are working with the supplier in order to remedy this issue as soon as possible.

The Notifier CFP-16 is currently the recommended replacement to the IFS-2600 FACP. The CFP-16 provides an easy to use and powerful detection and control system for all conventional detection applications.

Resources & Support:

Please contact your Honeywell Systems Consultant to discuss specific IFS-2600 FACP replacement application or support questions.

Technical questions should be directed to Honeywell technical support. **Tel: 1800 220 345 (Toll Free)**